



MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date: December 20, 2006

Supervisor DDH

Mine Name: Clark 1/Emeryide

Permit number: S0150053

Operator Name: Robert Clark

Inspection Date: December 15, 2006 **Time:** About 12:00 to 12:30 PM

Inspector(s): Paul Baker

Other Participants: Bob Clark

Mine Status: Inactive

Weather: Cloudy, 30s

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	\boxtimes	\boxtimes	
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control	\boxtimes		
4. Deleterious Material			
5. Roads (maintenance, surfacing, dust control, safety)			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads,			
highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other	\boxtimes	\boxtimes	

Purpose of Inspection:

The operator and I wanted to meet at the site and discuss the amount of reclamation surety that will be required.

Inspection Summary:

1. Permits, Revisions, Transfer, Bonds

The operator has not yet posted a reclamation surety, but we discussed the need and the amount. The deadline to obtain the surety was December 8, 2006.

12. Other

I used a GPS unit to map the disturbed area, and a copy of the map is attached to this report. The site consists of a small pad (0.27 acres), a road accessing this pad from above, and a road leading to one portal. The total disturbed area is about 0.5 acres.

Conclusions and Recommendations:

I told Mr. Clark I thought the Division's standard reclamation surety amount for one acre, \$5400.00, would probably be adequate. Essentially no grading would be required except to backfill the portal and the road leading to the portal. The rest of the area would simply need to be roughened and seeded. Since the site is on land managed by the Bureau of Land Management, I need to obtain their concurrence before giving a definite figure. I have not received a reply to my inquiry about the surety amount.

Inspection Date: December 15, 2006; Report Date: December 20, 2006

Page 2 of 2 S0150053

Inspector's Signature

PBB:pb

Bob Clark, Operator Rebecca Doolittle, Price BLM

Attachment: GPS Map

